Material Safety Data Sheet

May be used to comply with SHA's Hazard Communication Standard, 9 CFR 1910.1200. Standard must be consulted for specific requirements.

U.S. Department of Labor

Occupational Safety and Health Administration (Non-Mandatory Form) Form Approved OMB No. 1218-0072



IDENTITY (As Used on Label and List)
HONEY COMB TRAY PEGS Note: Blank spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that. Section I Manufacturer's Name Emergency Telephone Number National Keystone Products 800-535-5053 Address (Number, Street, City, State, and ZIP Code) 616 Hollywood Avenue Date Prepared Reviewed July 2006 July 2002 Cherry Hill, NJ 08002 Signature of Preparer (optional) Section II — Hazardous Ingredients/Identity Information Other Limits Hazardous Components (Specific Chemical Identity; Common Name(s)) OSHA PEL **ACGIH TLV** Recommended % (optional) N/A -Section III — Physical/Chemical Characteristics **Boiling Point** Specific Gravity (H₂O = 1) N/A N/A Vapor Pressure (mm Hg.) Melting Point N/A N/A Vapor Density (AIR = 1) Evaporation Rate N/A N/A (Butyl Acetate = 1) Solubility in Water None Appearance and Odor None Section IV — Fire and Explosion Hazard Data Flash Point (Method Used) Flammable Limits UEL N/A None Extinguishing Media N/A Special Fire Fighting Procedures N/A Unusual Fire and Explosion Hazards None

Section \	Special accordances to the con-								
Stability	Unstable		Conditions to A	void			s####		197/655
	Stable	X	und Actapio	ran en		i i albağılı		tyraäktikk	şh : All
Incompatib	ility (Materials to Av	oid)					ing as a cas		en trattigge
Hazardous (Decomposition or Byp	roducts	(1) (2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4						
Hazardous	May Occur	and the description	Conditions to A	void				ten jeni	
Polymerizati	Will Not Occur	ajan o (6) na hawar ar o	and the second s	transministration of the contraction of the contrac					
Caatian V	,	X							
Route(s) of B	<mark>/I — Health Haz</mark> Entry:	Inhalation?		Skin	•				
	rds (Acute and Chron	inl		ONI		Augusta, and august and analysis of the second seco	Ingestion	I.	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	ida (Acote and Cilion	Non	<u>é</u> mevoř						
The second second	Sugar Company						Albania a Sala		
									F Vigin
Carcinogenio	None l	VTP?		IARC	Monographs?		OSHA R	egulated?	
Signs and S	ymptoms of Exposure	None							
							aga ang ang disabat ang ang ang ang		
Medical Cond	ditions gravated by Exposure	None				e de la companya de l	energy (and the least of the		
acricially Ag	gravated by Exposure	none							100 E
a makama kang Pilipi						hain eidh is mar adhlig i misi	udijegamen emilionije de		proposition and bright
mergency a	and First Aid Procedu								and the same and
Section V	ind First Aid Procedur II — Precautions Taken in Case Materi	Flush	n with wate e Handling ar sed or Spilled	id Use					
Section V	II — Precautions Taken in Case Materi	Flush	n with wate e Handling ar sed or Spilled						
Section V	II — Precautions Taken in Case Materi	Flush for Saf	n with wate e Handling ar sed or Spilled N	id Use					
Section V	II — Precautions Taken in Case Materi	Flush for Saf	n with wate e Handling ar sed or Spilled	id Use					
Section V	II — Precautions Taken in Case Materi	for Safial Is Released	n with wate e Handling ar sed or Spilled N	id Use					
Section V	II — Precautions Taken in Case Materi Taken in Case Materi Taken in Case Materi	for Safial Is Released	n with wate e Handling ar sed or Spilled N	id Use					
Section V Steps to Be Vaste Dispose	II — Precautions Taken in Case Materi sal Method Norma Die Be Taken in Handling	for Safial Is Released	n with wate e Handling ar sed or Spilled N	id Use					
Section V Steps to Be Vaste Dispos	II — Precautions Taken in Case Materi sal Method Norma	for Safial Is Released	n with wate e Handling ar sed or Spilled N	id Use					
Section V Steps to Be Vaste Dispos Precautions to	II — Precautions Taken in Case Materi sal Method Norma Discrete Taken in Handlin slions None	es Flus! i for Safe at is Releas I trash	n with wate e Handling ar sed or Spilled N	id Use					
Section V Steps to Be Vaste Dispose Precautions to Other Precaut	II — Precautions Taken in Case Materi sal Method Norma Die Be Taken in Handlin tions None II — Control Mea	es Flush for Safe for	n with wate e Handling ar sed or Spilled N	id Use					
Section V Steps to Be Vaste Dispose Precautions to Section VII espiratory Pr	II — Precautions Taken in Case Materi all Method Norma be Be Taken in Handlii tions None II — Control Mea	es Flush for Safe for	n with wate e Handling ar sed or Spilled N	id Use					
Section V Steps to Be Vaste Dispose Precautions to Section VIII	II — Precautions Taken in Case Materi all Method Norma be Be Taken in Handlii tions None II — Control Mea totection (Specify Type Local Exhaust	es Flusi for Safe al is Releas l trash ng and Sto asures N/A	n with wate e Handling ar sed or Spilled N	id Use	Special				
Section VI Steps to Be Vaste Dispose Precautions to Other Precaution Section VIII Despiratory Precaution	II — Precautions Taken in Case Materi Taken in Case Materi Taken in Case Materi Norma Discrete Taken in Handlin Discrete Tak	es Flusi for Safe al is Releas l trash ng and Sto asures N/A	n with wate e Handling ar sed or Spilled N	id Use	Special Other				
Section VI Steps to Be Vaste Dispose Vaste Dispose Vather Precautions to the Precautions to the Precaution VIII Section VIII Section VIII Septimatory Presentilation	II — Precautions Taken in Case Materi Taken in Case Materi Taken in Case Materi Norma Discrete Taken in Handlin Discrete Tak	es Flusi for Safe al is Releas l trash ng and Sto asures N/A	n with wate e Handling ar sed or Spilled N	id Use	A company of the second				
Section VI Sleps to Be Vaste Dispose Precautions to Section VII Despiratory Presidentiation	II — Precautions Taken in Case Materi Taken in Case Materi Taken in Case Materi Norma Discrete Taken in Handlin Discrete Tak	es Flush for Safe al is Releas L trash ng and Sto asures N/A	n with wate e Handling ar sed or Spilled N	id Use	Other				
Section VI Steps to Be Waste Dispose Precautions to Description VII Respiratory Pr Pentilation rotective Glowther Protective	II — Precautions Taken in Case Materi Taken in Case Materi Taken in Case Materi Norma Discrete Taken in Handlin None Local Exhaust Mechanical (Gene Ves	es Flush for Safe al is Releas L trash ng and Sto asures N/A	n with wate e Handling ar sed or Spilled N	id Use	Other				
Section VI Steps to Be Waste Dispose Precautions to Other Precaut Section VII Respiratory Precautions Totective Glove	II — Precautions Taken in Case Materi Taken in Case Materi Taken in Case Materi Norma Discrete Taken in Handlin None Local Exhaust Mechanical (Gene Ves	es Flush for Safe al is Releas L trash ng and Sto asures N/A	n with wate e Handling ar sed or Spilled N	id Use	Other			JSGP.0 1986 -	